



My Notifications

< [Back to Previous Page](#)

CSCtf02842 has been superseded by CSCtb03932 displayed below.

CSCtb03932 Bug Details

IDSМ - loses clock sync with the NTP server

Symptom:

In some situation IDSМ loses the clock sync w ith the NTP server

Conditions:

If the sensor time offset (from the NTP server) becomes greater than 1000 secs then ntpd will abort (according to NTP design).

Workaround:

none

Further Problem Description:

The sensor can be recovered (ntpd restarted and synched to the NTP server) by:
1) Reboot the sensor
2) In svc acct, "su" to root (same PW as svc acct PW), run "/etc/init.d/cids restart"
3) Re-enter or change NTP config and then save

Related Bug Information

ntp daemon may lose synchronization with server

Symptom: When ntp is enabled, the sensor's clock may intermittently lose and regain synchronization w ith the server, or it may lose synchronization permanently. In addition the time required to synchronize w ith an ntp server is unnecessarily long.
Conditions: Loss of synchronization may occur if the ntp server is configured w ith a stratum value of 5 or greater. **Workaround:** Use an ntp server w ith a stratum value less than 5 or change the configuration on the ntp server to fudge it's stratum to a value less than 5. Note: the cause of the problem is an error in the values that mainApp w rites to the file /etc/ntp.conf. How ever editing the /etc/ntp.conf file on the sensor using the service account is not a good w orkaround because mainApp w ill overw rite the changes to that file each time mainApp starts up.

Interpreting This Bug

Bug Toolkit provides access to the latest raw bug data so you have the earliest possible knowledge of bugs that may affect your network, avoiding un-necessary downtime or inconvenience. Because you are viewing a live database, sometimes the information provided is not yet complete or adequately documented. To help you interpret this bug data, we suggest the following:

- This bug has a **Moderate** severity 3 designation. Things fail under unusual circumstances, or minor features do not work at all, or things fail but there is a low -impact w orkaround.
- This is the highest level for documentation bugs. (Bug Toolkit may not provide access to all documentation bugs.)
- Severity levels are designated by the engineering teams w orking on the bug. Severity is not an indication of customer priority w hich is another value used by engineering teams to determine overall customer impact.
- Bug documentation often assumes intermediate to advanced troubleshooting and diagnosis know ledge. Novice users are encouraged to seek fully documented support documents and/or utilize other support options available.

[Save Bug](#) Save this bug and set email notifications

Give us feedback.

Please rate your overall experience w ith Bug Toolkit (include the search experience, setting notifications for bugs, ease of getting to bug information, etc).

☐ Excellent ☐ Good ☐ Average ☐ Fair ☐ Poor

Were the bug details provided in your search results effective in solving your problem ?

☐ Yes ☐ No ☐ Just brow sing

Please provide us w ith suggestions to improve the Bug Content Details or the Bug Toolkit experience:

☒ You may contact me regarding my feedback

Full Name:

Ajith Rajan

Email:

ajith.rajana@mannai.com.qa

[Send Feedback](#)

Status

Open
(Postponed)

Severity

3 - moderate

Last Modified

In Last Year

Product

Cisco IPS 4200
Series Sensors

Technology

1st Found-In

6.0(1)
6.1(2)
7.0(1)
7.0(1)S1
7.1(0)B1

Component(s)

other