

## Power Controller reports Short detected when non PoE device connected

CSCuo83872

## Description

## Symptom:

We will get syslog messages:

Mar 16 08:08:29 10.13.36.1 3028812: Mar 16 08:10:49.079 EDT: ILPOWER-3-CONTROLLER\_PORT\_ERR Controller port error, Interface Gi3/0/16: Power Controller reports Short detected

Mar 16 08:08:29 10.12.233.1 464666: Mar 16 08:10:15.220 EDT: ILPOWER-3-CONTROLLER\_PORT\_ERR Controller port error, Interface Gi3/0/3: Power Controller reports Short detected

Mar 16 08:08:29 10.13.18.1 423165: Mar 16 08:10:57.031 EDT: ILPOWER-3-CONTROLLER\_PORT\_ERR Controller port error, Interface Gi2/0/4: Power Controller reports Short detected

## Conditions:

Sometimes when non PoE devices are connected to a 3850/3650 PoE port. Syslog messages are considered to be cosmetic.

## Workaround:

The "power inline never" command stops the syslog messages.

## Further Problem Description:

Was the description about this Bug Helpful? ★★★★★ ☆ (3)



Customer Visible



Save Bug



Open Support Case

## Details

Last Modified: Dec 17, 2014

Status: Fixed

Severity: 5 Cosmetic

Product: Cisco Catalyst  
3850 Series Switches

Support Cases: 42

Known Affected Releases: (1)

3.3(2)SE

Known Fixed Releases: (15)

15.0(14.5)E2J

15.2(2)E

15.2(2.3)PSR

15.2(2.39)PSR

15.2(2b)E

15.2(3)E

3.3(4)SE

3.3(5)SE

3.6(0)E