



PORTABLE PRODUCT SHEETS – POWER

Last Updated June 7th 2007

Country	Voltage	Power Supply Suffix
Argentina	220	ACR
Aruba	110	ACE
Australia	220	ACA
Austria	220	ACE
Belgium	220	ACE
Bermuda	120	AC
Brazil	110	AC
China	220	ACA
Chile	220	ACE
Columbia	110	AC
Czech Republic	220	ACE
Costa Rica	120	AC
Denmark	220	ACE
Dominican Republic	110	AC
Ecuador	120	AC
Finland	220	ACE
France	220	ACE
Germany	220	ACE
Greece	220	ACE
Guatemala	120	AC
Hong Kong	200	ACU
Hungary	220	ACE
Iceland	220	ACE
India	220	ACE
Indonesia	220	ACE
Ireland	220	ACU
Israel	230	ACE



PORTABLE PRODUCT SHEETS – POWER

Last Updated Oct 2th 2007

Country	Voltage	Power Supply Suffix
Italy	220	ACI
Japan	110	AC
Korea	220	ACE
Luxembourg	220	ACE
Malaysia	240	ACE
Mexico	110	AC
Monaco	220	ACE
Netherlands	230	ACE
New Zealand	230	ACA
Norway	220	ACE
Panama	110	AC
Peru	220	ACE
Philippines	220	ACE
Puerto Rico	220	AC
Romania	120	ACE
Russia	220	ACE
Singapore	220	ACE
Slovakia	230	ACE
South Africa	220	ACE
Spain	220	ACE
Sweden	220	ACE
Switzerland	220	ACS
Taiwan	220	AC
Thailand	110	ACE
United Kingdom	220	ACU
Venezuela	230	AC
Vietnam	120	ACU

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International
BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R)

Printed in the USA